

<b>SB Number:</b>	<b>SB 2G6-001</b>	<b>Creation Date:</b> 27/01/2006
<b>Subject:</b>	<b>Firmware upgrade (SYS), version 002.001</b>	
<b>Model:</b>	<b>FS-1030D</b>	

System Firmware is upgraded as follows.

## Contents of changes

No.	Contents	Remarks
1	Drop-out print image at the right bottom corner on Quark Xpress 6.5	The data is of PostScript level 1. Handling of operators and clipping are incorrect. (Corrected)
2	Change from Draft mode to EcoPrint mode	PJL readback and status pages now show EcoPrint
3	Toner Coverage Information	Toner coverage information is now indicated.

Type	Program number	Check SUM	Version	Remarks
System	S2G6_3000002001	0759	002.001	

## Field Measure:

If the problem arises, please upgrade firmware.

## Affected machine serial numbers:

XLL5Z10806 and higher.