
Model:**LaserBase MF8180C****Ref No.:**

MF8180C-001

(SH-T01-OCT-10012-01)

Date:March 2006

Location:

Driver

Subject:

Modification of installation error which occurs when the old MF8180C driver is installed

Detail:

<Phenomenon>

In the environment which OS is Windows 98/ Me and a device common driver (UFR II Ver. 1.50 or later, FAX Ver. 3.88 or later) is installed, execute the USB installer for MF8180C.

At the USB connection, the plug-and-play screen appears and a message recommending you to use the existing file is displayed. If you select "No" and install the old driver, "Properties" of the device common driver which is already installed cannot be opened.

<MF8180C-dedicated driver>

Ver. 1.31

<Error occurrence>

OS: This error occurs with Windows 98/ Me.

I/F: This error occurs when installing by USB cable.

Target device: MF8180C

<Recovery method>

When this error occurs, reinstall the device common driver.