


<b>SB Number:</b>	<b>SB 2BX-003</b>	<b>Creation Date:</b> 06/04/2004
<b>Subject:</b>	Improve paper transport (change SPRING ACTUATOR REG')	
<b>Model:</b>	FS-1010, FS-1050	

In order to improve the reliability of paper transport in the FS-1010/1050, the 'SPRING ACTUATOR REG' has been changed as follows.

**Content of change**

Spring load has been reduced.



No.	Part No. OLD	Part No. NEW	Description	Q'ty old-new		Interchange ability	
1	5MMW151LD005	5MMW261LD057	SPRING ACTUATOR REG	1	1	O	O

**Affected Machine Serial Numbers:**

**FS-1010:** XAL2155343 and later

**FS-1050:** XAM2210519 and later