

SB Number:	SB 2G6-002	Creation Date: 30/06/2006
Subject:	Firmware upgrade, Ver. 003.002 (system)	
Model:	FS-1030D	

The system Firmware is upgraded as follows:

Contents/corrections:

1. When certain PS files are sent to the printer two times in a row, the second document is incorrect;
2. When outputting any HPGL2 file, the output position of the character line is not correct;
3. When outputting certain PS files, a KPDL error occurs.

All of the above phenomena have been corrected.

Type	Program number	Check SUM	Version	Remarks
System	S2G_63000003002	A359	003.002	-

Current Version: 002.001

Field Measure:

If the problem arises, please upgrade firmware.

Affected machine serial numbers:

XLL6500001 and higher