

SB Number:	SB 2H4-003	Creation Date: 19/05/2009
Subject:	<i>Engine firmware upgrade version 003.002 (grey background on the print-out)</i>	
Model:	FS-1350DN	

Contents of changes		Item	Contents
	1	Grey background on the print-out.	Grey back ground may appear on the print-out, when outputting large print jobs after replacing the toner.

Firmware	Type	Program No.	Check SUM	Version
V.003.002	ENGINE	S2H4_1000003002	29EE	003.002

Classification	<input type="checkbox"/> Entire stock rework	<input type="checkbox"/> In-field modification at next visit	<input type="checkbox"/> In-field modification by case	<input checked="" type="checkbox"/> No modification necessary
Field measure	When the above mentioned phenomenon occurs, please upgrade the firmware to the latest version.			

Affected serial numbers	Type	Serial number
	FS-1350DN	Not available