



# KYOCERA Service Bulletin

<b>SB Number:</b>	<b>SB 2HS-007</b>	<b>Creation Date: 03/06/2010</b>
<b>Subject:</b>	<b>Latest registered service part</b>	
<b>Model:</b>	<b>FS-1100/1300D</b>	

To improve the production efficiency, the **roller heat set** has been registered. When replacing the roller heat, please use the **roller heat set** and replace the gear and bush at the same time.

## Parts

No.	Old Parts No.	New Parts No.	Description	Q'TY		Interchangeability		SP
				Old	New	Old	New	
1	-----	302HS94290 2HS94290	ROLLER HEAT SET	-	1	-	O	O
2	302HS25230 2HS25230	302HS25231 2HS25231	+ROLLER HEAT	1	1	O	O	X
3	302HS93040 2HS93040	302HS93041 2HS93041	FK-130(E)	1	1	O	O	O