



SB Number:	SB 2HS-002	Creation Date: 14/01/2009
Subject:	<i>Paper jam, actuator of registration sensor does not move freely</i>	
Model:	FS-1100/1300D	

Phenomenon	A paper jam may occur if the actuator of registration sensor (302HS24060) does not move freely.
-------------------	---

Cause	The projections of the bush DU may move inwards, resulting in that the bush DU drops from the base frame, pushing the actuator of registration sensor downwards. This may occur when the machine receives a shock (E.G. machine is dropped on a surface).
--------------	--

Solution	Place sheet bush DU between the bush DU projections to improve the fitting.
-----------------	---



Parts	No.	Old Parts No.	New Parts No.	Description	Q'TY		Interchangeability		SP
					Old	New	Old	New	
	1	-----	302HS02700 2HS02700	SHEET BUSH DU	-	1	-	O	-